1Febryary 2016 By: KG

STOCKMAN STONEWORKS



Build Guide

TOOLS


SQUARE CAULK GUN 4 FOOT LEVEL
DEAD BLOW HAMMER


Item List

Simplicity 12x8x4 68ea Simplicity 12x4x4 2ea


Double Vyking Cap 26"x12"x3" 3ea Outer Cap 12"x5"x3" 6ea

PL Glue 5 Tubes





"For ease of installation a cement pad is recommended." If concrete is not an option a pad of gravel will suffice. Insure to use a 1" Rock or comparable size, at least 2 inches thick, compacted on solid ground. Using a straight edge (i.e. 4' level or 2 x 4 Square) pick a starting side and begin leveling your blocks one at a time, using your straight edge as a guide.






Once your base is level, thoroughly brush off the top to ensure proper bonding. Clean your second layer blocks also and begin laying your second course, gluing all blocks. Gluing sides is not necessary. Again use your straight edge and square to keep everything plumb.

Important Note As you glue, gently tap block with your Dead blow to evenly distribute the glue between adjoining faces.

Important Note Take Caution, as freshly glued blocks will easily slide around until glue begins to set.





Simplicity


21

Glue

Again insure all blocks to be glued are thoroughly brushed and clear of dust. Begin at either corner and construct the back section first, gluing all touching blocks.














Again insure all blocks to be glued are thoroughly brushed and clear of dust. Begin at either corner and construct the back section first, gluing all touching blocks.

















Final

